

Oil Field Environmental Incident Summary

Incident: 20150417090344 **Date/Time of Notice:** 04/17/2015 09:03

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: WINCHESTER 43-8SH

Field Name: CEDAR HILLS

Well File #: 27121

Date Incident: 4/16/2015 **Time Incident:** 08:13

Facility ID Number:

County: BOWMAN

Twp: 132

Rng: 106

Sec: 8

Qtr:

Location Description: Pasture west of pipeline ROW and south of well pad.

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels
Brine	6	Barrels	6	Barrels	6	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/13/2015

Clean Up Concluded: 4/20/2015

Risk Evaluation:

None

Areal Extent:

20' x 30', 30' x 50', 2' x 30'

Potential Environmental Impacts:

Topsoil in pasture

Action Taken or Planned:

Visibly contaminated material was removed. Soil samples will be taken on April 20.

Wastes Disposal Location: Little Missouri Special Landfill

Agencies Involved:

Updates

Date: 4/17/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pipeline leak, along pipeline right of way. Followup is necessary.

Date: 4/21/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 14:18 p.m. The weather was clear, 48 °F, with the wind from the north 5-10 mph. I talked to the area supervisor for the company; he indicated that this is a second break on this pipeline from this well. They have replaced the rest of the pipeline in this area with a different style of pipeline. The first spill was right next to the south side of pad. This spill was southwest of the well, located on east side lease road where it meets the other lease road. The spill was in the pipeline right of way; the cleanup crew is removing a little more impacted soil. The consultant will return to take samples to verify cleanup. The impacted soil is being stacked next to the first pile of soil. The supervisor indicated that it has been cleared by the landfill and will be hauled away the next couple of days. Further followup is needed to check on pipeline reclamation. 46.10564; - 103.85695

Date: 6/9/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/9/2015 at 20:03, on location. Pipeline has been backfilled, graded, and replanted. No visible oil staining on pipeline or new vegetation, though some brown staining is visible. This staining appears to be from fertilizer/amendment added to the replanted vegetation because it is visible in areas of more growth and lacking in areas where vegetation is not as lush.

Date: 7/15/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 11:24 a.m. The weather was sunny, 83°F, with the wind from the southwest 0-5 mph. The vegetation has come back along the pipeline right of way. No further follow-up needed at this time.

Date: 3/9/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.